



Photo 1. The Pu'ukua Lot, at the Traditional Hawaiian Hale location. Looking east into the valley.



Photo 2. Facing east at the location of the rockfall mitigation behind the Community Resource Center




Photo 3. Facing northwest at the rockfall mitigation location behind the Community Resource Center



Photo 4. Facing south at the existing Sewer Treatment Plant (STP) area.



Photo 4. The pathway leading to the STP area showing the existing STP. The Future STP will be located between the photographer and the fence.



PIKAKE PAVILION




VISITOR CENTER GIFT SHOP



COMMUNITY RESOURCE CENTER



VISITOR CENTER RESTROOMS



USGS MAP  
RETRIEVED FROM:  
<https://apps.nationalmap.gov/downloader/#/>  
on 10/13/2023

1 PICTURES OF STRUCTURES TO BE IMPROVED

2 PROJECT LOCATION